

車 名	年 式	型 式		架装形状			整理番号	
いすゞ	05/03	2PG-FRR90S2		平ボディ ー				
車検有効期限	走行距離 (km)		積載量	タコグラフ年月	荷台寸法 (mm)			48818
R08.3.15	50,213 km		3,950 kg		長さ	幅	高さ	
	リサイクル料金		12230 円		6,210	2,150	400	

エンジン状態	B	エンジン	4気筒/ターボ	ブレーキ	エア	210 馬力	ミッション	6速 3ペダル	キャブ内汚れ	少
ミッション・デフ状態 OK									シート汚れ	無し
フレーム関係・下回り状態 OK									フロントガラス状態	飛石有
上物 (メーカー・型式・年式) パブコ									キャブ内装備	
仕様等 自社レンタUP★標準巾・フック4対・ロープフック(サイド14対、後ろ3ヶ)・セイコーラック・アオリ3方開									ETC2.0 キーレス 集中ドアロック	

その他・備考欄

記録簿
なし
メンテナンスノート
あり

The image contains three line drawings of a truck for inspection purposes. The top drawing is a front view with labels 'パー曲面' (Lower fender curve) and '板ハガレ' (Panel peeling). The middle drawing is a side view with labels 'カンバン跡' (Tag mark) at the front, '一部小凹み' (Small indentation) on the chassis, and 'バンパー曲面 (小)' (Small bumper curve). The bottom drawing is a rear view with a label 'カンバン跡' (Tag mark) at the rear. To the right of the side view are two empty rectangular boxes, with the top one labeled '凹み (小)' (Small indentation) pointing to a small circle inside it.

タイヤ状態 (mm、欠、で記載)				
9	前	5		
5	5	5	5	
スペア	F	11	R	
種類	サマー			
サイズ F	225/90 R 17.5			
サイズ R	225/90 R 17.5			
アルミホイール	無			